



LSC ELECTRONICS PTY LTD

65-67 Discovery Road,  
Dandenong South,  
Victoria Australia 3175

T +61 (0)3 9702 8000  
F +61 (0)3 9768 2631

info@lsclighting.com.au  
www.lsclighting.com.au

ABN 50 006 231 287

## LSC R&D DEPARTMENT – SOFTWARE RELEASE NOTE

Project Title: **Red3 Dimmer**

Written by : Gary Pritchard  
Last Modified: 08-May-2017

This document is a list of software changes for Red3 Dimmer firmware.

### Reporting Bugs

If you find a bug, or feel that we could improve the dimmer then please let us know. If you find a bug that affects operation or crashes the dimmer, then could you let us know ASAP!!

Email : techSupport@lsclighting.com.au  
Phone : +61 3 9702 8000  
Fax : +61 3 9768 2631

### Obtaining Updates

If you wish to be emailed firmware updates as they are released, then send an email to the above address and you will be added you to the mailing list.

### **Release 1.02 Date 08-May-2017**

Reason for the Release: 

- Bug Fix

Bug Fixes: 

- After an amount of time, channels could change operation to be reverse phase. The time taken for this to happen is completely random but anecdotally it occurs in most situations after a few hours of operation.

Features Upgraded: 

- None

Known Bugs: 

- None

### **Release 1.01 Date 02-Sep-2016**

Reason for the Release: 

- Bug Fix

Bug Fixes: 

- 6-channel configuration was incorrect.

Features Upgraded: 

- None

Known Bugs: 

- None

### **Release 1.00 Date 24-Aug-2016**

Reason for the Release: 

- First public release.

Bug Fixes: 

- N/A

Features Upgraded: 

- N/A

Known Bugs: 

- None.
-

**- END -**