

Project Title: LscNet Toolbox

Written by : Dejan Deletić
Last Modified : 12 October 2010

This document is a list of bug fixes and feature enhancements for LscNet Toolbox program. This program serves as an application launcher for several LscNet tools, including:

- CodeNet
- ePlate Editor
- Lsc232

Reporting Bugs

If you find a bug, or feel that we could improve the dimmer then please let us know. If you find a bug that affects operation or crashes the dimmer then could you let us know ASAP!!

email techSupport@lsclighting.com.au
fax +61 3 9702 8000
phone +61 3 9702 8466

Obtaining Updates

If you wish to be emailed 'LscNet Toolbox' updates as they are released then send an email to the above address and you will be added you to the mailing list.

Release 1.01 Date 12-Oct-2010

Reason for the Release: Bug fixes

Bug Fixes:

Toolbox (released as v1.01)

- None.

CodeNet (released as v1.15)

- File selection drop down list on Configuration and Firmware tabs is now re-populated prior to being displayed, rather than being static.

ePlate Editor (released as v1.01)

- When fade time is unticked, edit box is set to 0
- 'Save to ePlate' checks plate type. Ditto for 'Get from ePlate'
- Added message box to inform that 'Save to ePlate' transfer has been completed.
- Manual updated
- 'Control Source Select' page now displays group number edit box (Mantis #980).
- Added descriptive tooltips for Action nodes in the tree.
- Removed 'Radio Buttons' - this feature has not and will not be implemented in ePlates.
- Indicator source forced to LevelEquals when 'Link with Button' is selected.
- Indicator operation forced to action's operation instead of None when 'Link with Button' is selected.
- Disabled 'Set Memory With Value' for button memories
- Implemented various default indicator configurations for 'Link With Button'
- Added a tick box to Indicator dialog to select if the indicator is unused
- Improved 'Item Selection' dialog.
- Copy/Paste of button information now includes Indicators.

Lsc232 (released as v1.00)

- None.

Release 1.00 **Date 12-Jul-2010**

Reason for the Release: This is the first release

Bug Fixes:

Toolbox (released as v1.00)

- None. This is the first release

CodeNet (released as v1.14)

- When opening file in the Configuration Tab, it no longer provides file mask to allow users to select any xml file.
- Fixed issues with testing 2B1F, 2B2F, 4B1F and 4B2F ePlates (Mantis #804).

ePlate Editor (released as v1.00)

- None. This is the first release

Lsc232 (released as v1.00)

- None.

Features Upgraded:

Toolbox

- None. This is the first release

CodeNet

- Implemented Learn Mode - helps in pairing IP addresses and their locations around the installation building.
- Implemented SendCommand function.
- Port selection dialog now defaults to listing 'PC link' devices only.
- Configuration 'Send' operation is aborted if ePlate firmware is earlier than a minimum required (currently 2.56).

ePlate Editor

- None. This is the first release

Lsc232

- None.

- END -